

Village of Pinecrest

Permit Corrections Report: BL2023-1640
April 2, 2024

Review Type: **Building**
Revision No. 2



Casa Ohad

6200 SW 123 Terrace

Pinecrest, Florida 33156

Date of Comments **02-21-2024** (Second Round)

Reviewer: **Paul Buckler**

1. Attic insulation required to be applied on underside of roof structure. Unfortunately, we provided misinformation. the comment remains. Note most projects with similar roof conditions use spray foam as the mechanics of attaching batt insulation is problematic.
[We have revised drawings to show spray foam insulation.](#)

[Please refer to Revision #2 on Sheet A-301, A-302, and A-410](#)

The following sheets have been revised and submitted in order to satisfy the above-mentioned Building comments:

Sheet Drawings:

- [A-301, A-302, and A-410](#)

Documents:


- N/A

I thank you in advance for your time on this matter.

Regards,



Felipe Alvarado, R.A., LEED AP



FAO ARCHITECTURE, LLC
407 LINCOLN ROAD SUITE 8-S
MIAMI BEACH, FLORIDA 33139
AR 91841

TEL 786.448.5630
DESIGN@FAOARCHITECTURE.COM