

ANSWER TO MECHANICAL COMMENTS 08-25-22

Calculations show roof vented, plans show unvented

Answer: refer to revised energy and heat load calculations

Sheet M-2 Incomplete

Answer: The sheet M-2 is completed, refer to sheet M-2 just in case during upload process it was corrupted