

10635 SW 63 AV
MIAMI, FL

SEAL

GIORGIO LUIGI BALLI -AR13951
DAVID SCOTT TRAUTMAN -AR15045

NO.	DESC	DATE
1	Public Works ROW Comments	03.17.25
2	Planning Comment Exist. Trees to Remain Rev. Plant List, Driveway Dimensions, & FFEs	05.16.25
3	Planning Comment Text Clarity, Dim.	06.18.25
4	Planning Comment Rev. TSTD calc & CD Tree Replacement	07.18.25


BALLI - TRAUMA
ARCHITECTURE INTERIORS CONSTRUCTION

CHECKED BY: GE

SCALE: AS NOTED

SHEET NUMBER

COPYRIGHT BALLI-TRAUTMAN ARCHITECTS,
LLC
1533 SUNSET DRIVE SUITE 101, CORAL GABLE
FL 33143



H.L. Martin, Landscape Architect, P.A.
LC# 26000404 LA #0001722
5965 SW 38th Street, Miami, Florida 3315
305 790-4372, hlmartinufu@bellsouth.net

Herbert L. Martin, Landscape Architect

L 101 Landscape Plan
L 102 Notes, Details, Legend
L 103 Tree Survey / Disposition Plan
L-104 Tree Disposition & Protection
L-105 Irrigation Plan

