

LEGEND



SKIMMER DETAIL

NO SCALE



-WARNING: TO EMPTY POOL AFTER CONSTRUCTION FOR REPAIRS OR ANY OTHER REASON, THE HYDROSTATIC UPLIFT PRESSURES BENEATH THE POOL MUST BE ELIMINATED TO PREVENT THE POOL FROM FLOATING UPWARD. THE OWNER MUST CONSULT AND POOL REPAIR CONTRACTOR EXPERIENCED IN ELIMINATING UPLIFT PRESSURES.

SYMBOL	NAME	QTY
	RETURN	7
	THERAPY JET	10
	VACUUM WITH SPRING LOADED COVER	1
		1
	CHANNEL MAIN DRAIN	2
	NICHELESS POOL LIGHT 20W 120VLT	6

PRINTED COPIES OF THIS DOCUMENT ARE NOT
CONSIDERED SIGNED AND SEALED AND THE
AUTHENTICATION CODE MUST BE VERIFIED ON AN
ELECTRONIC COPIES.