

10635 SW 63 AV
MIAMI, FL

SEAL

BALLI-TRAUTMAN ARCHITECTS LLC -AA2600

GIORGIO LUIGI BALLI	-AR13951
DAVID SCOTT TRAUTMAN	-AR15045

REVISIONS

[illegible]

BALI - TRAUTMAN
ARCHITECTURE INTERIORS CONSTRUCTION

JOB NUMBER:

CHECKED BY: _____

ISSUE DATE: 11/11/2024


SCALE: AS NOTED

SHEET TITLE

SHEET NUMBER



L 104

COPYRIGHT BALLI-TRAUTMAN ARCHITECTS,
LLC
1533 SUNSET DRIVE SUITE 101, CORAL GABLES
FL 33143



1

SCALE: 1" = 16'-0"



TREE PROTECTION BARRIER DETAIL

N.T.S.

Notes:

- 1) Tree Protection Barriers dimensions are measured from the center line of the trunk. (as per Arborist's Report)
- 2) Tree Protection Barriers are placed where necessary to enclose buildings, adjacent sidewalks, & street/curb.
- 3) No disturbance to soil or disposal of any building material/waste is permitted within the tree protection zone.
- 4) Barriers to remain in place throughout the duration of construction or demolition activities.
- 5) Barriers to be attached to existing GLF's, WD fences or concrete walls where applicable.

Tree Survey List

Num	Botanical / Common Name	Description				TPZ/CRZ Size (ft ²)	Notes	Disposition	Explanation/ Reason	Canopy SF To Be Removed	DBH > 18" (x 2) To Be Removed
		HT	DBH	SpC	Condition						
#1 QV	Quercus virginiana / Live Oak	30'	25'	12"	Good	6'	R/W Tree	Remain			
#2 QV	Quercus virginiana / Live Oak	35'	35'	12"	Good	6'	R/W Tree	Remain			
#3 QV	Quercus virginiana / Live Oak	30'	30'	12"	Good	6'	R/W Tree	Remain			
#4 BS	Bursera simaruba / Gumbo Limbo	25'	18'	12"	Good	6'		Remain			
#5 QV	Quercus virginiana / Live Oak	30'	30'	12"	Good	6'		Remain			
#6 QV	Quercus virginiana / Live Oak	30'	30'	12"	Good	6'		Remain			
#7 QV	Quercus virginiana / Live Oak	30'	30'	12"	Good	6'		Remain			
#8 QV	Quercus virginiana / Live Oak	30'	30'	12"	Good	6'		Remain			
#9 QV	Quercus virginiana / Live Oak	30'	35'	18"	Good	9'		Remain			
#10 QV	Quercus virginiana / Live Oak	35'	30'	12"	Good	6'		Remain			
#11 QV	Quercus virginiana / Live Oak	40'	30'	12"	Good	6'		Remain			
#12 QV	Quercus virginiana / Live Oak	30'	30'	18"	Good	9'		Remain			
#13 QV	Quercus virginiana / Live Oak	30'	30'	12"	Good	N/A		Remove	building footprint	707 sf	
#14 QV	Quercus virginiana / Live Oak	30'	30'	12"	Good	N/A		Remove	pool deck footprint	707 sf	
#15	Palm	30'	10'	8"	Good	4'		Remain			
#16 QV	Quercus virginiana / Live Oak	35'	20'	12"	Good	N/A		Remove	drainfield footprint	314 sf	
#17 QV	Quercus virginiana / Live Oak	30'	30'	12"	Poor	6'		Remain			
#18 QV	Quercus virginiana / Live Oak	30'	30'	12"	Good	6'		Remain			

Tree Survey Notes:


- 1) Tree Descriptions (ht, spr, dbh) are as per Survey prov'd to LA, dated 06.26.2024. by Suarez Surveying & Mapping, Inc. AFA & Company, Armando Alvarez, 06.26.2024.

1,728 sf required


Total Canopy to be Removed < 18" dbh	Specimen trees to be Removed > 18" dbh
1	1
2	1
3	1
4	1
5	1
6	1
7	1
8	1
9	1
10	1
11	1
12	1
13	1
14	1
15	1
16	1
17	1
18	1
19	1
20	1
21	1
22	1
23	1
24	1
25	1
26	1
27	1
28	1
29	1
30	1
31	1
32	1
33	1
34	1
35	1
36	1
37	1
38	1
39	1
40	1
41	1
42	1
43	1
44	1
45	1
46	1
47	1
48	1
49	1
50	1
51	1
52	1
53	1
54	1
55	1
56	1
57	1
58	1
59	1
60	1
61	1
62	1
63	1
64	1
65	1
66	1
67	1
68	1
69	1
70	1
71	1
72	1
73	1
74	1
75	1
76	1
77	1
78	1
79	1
80	1
81	1
82	1
83	1
84	1
85	1
86	1
87	1
88	1
89	1
90	1
91	1
92	1
93	1
94	1
95	1
96	1
97	1
98	1
99	1
100	1

1,728 sf

0 sf



—Existing Tree / Palm to remain.
CRZ, (Critical Root Zone)
(dim. from face of trunk)



—Existing Tree / Palm to be removed.