



Eastern Engineering Group

3401 NW 82nd Ave.
Suite 370
Doral, FL. 33122
(305) 599-8133
info@easterneg.com
www.easterneg.com

Date: April 25th, 2025

To: Building Official
City of Miami Building Department

RE: 13100 SW 80th Ave, Miami, FL 33156
Response to Comments – Process Number BL2025-0117

1. **Please provide special inspector form for reinforced masonry, soil compaction, welding.**

The special inspector Form has been provided

2. **Sheet S-2 steel base plate should be 1" thick per calcs. and schedule see detail on plan make correction**

The steel base plate has been updated on sheet S-2.0 under revision #1

3. **provide reinforcing and details for support of stair concrete floating steps**

The detail G/S-4.1 has been updated on sheet S-4.1, and the stair section has also been updated on sheet S-3.3 under Revision #1

4. **Submit geotechnical report digitally signed with soil capacity.**

The geotechnical soil report has been provided by the owner or the architect.

If you have questions or require additional information, please do not hesitate to contact our office for further assistance.

Sincerely,

Raissa R. Lopez, PE
Lic No. 59399