

RESPONSE LETTER

Permit #BL2025-1559

Date: 12/01/2025

BUILDING EXPEDITE

- 1.Pool barrier shown on SP-1 has opened on southwest corner of property. Please clarify.
R. Done. See SP-1 Plan.
- 2.Submit pool alarm manufacturer's spec sheets. **R. DONE. See Spec sheets attached.**

ZONING EXPEDITE.

1. Submit in progress signed and sealed survey of the property. **R. Done. See SURVEY attached.**
2. Provide details of all fencing and gates being used as approved zoning pool barrier. **R. Done. See SD-1 Plan.**
3. Provide height of pool equipment and height of enclosure. **R. Done. See SP-1 Plan.**

STRUCTURAL

1. Review section E/SP-3 reinforcing and size of structural members not shown for structure supporting steps. clarify if continuous. **R. Done. See SECTION E AND SECTION G in SP-3 Plan.**
2. What is fill under structure in item #1. **R. Done. See SECTION E AND SECTION G in SP-3 Plan.**
3. Tie in missing at vertical and horizontal members **R. Done. See SECTION E AND SECTION G in SP-3 Plan.**